

FINAL REPORT

**WATERSHED ASSESSMENT OF
LOWER BUSH CREEK
FREDERICK COUNTY, MARYLAND**

Prepared for

Frederick County
Division of Public Works
Office of Development Review
118 North Market Street
Frederick, Maryland 21701-5422

Prepared by

Nancy Roth
Morris Perot
Emily Rzemien

Versar, Inc.
9200 Rumsey Road
Columbia, Maryland 21045
and
Philip Hopkins
The Greeley-Polhemus Group, Inc.
105 South High Street
West Chester, Pennsylvania 19382-3226

March 2001

TABLE OF CONTENTS

	Page
1.0 INTRODUCTION	1-1
2.0 METHODS	2-1
2.1 <u>Stream Assessment Field Methods</u>	2-1
2.1.1 Stream Monitoring Stations	2-3
2.1.2 Chemical Water Quality Sampling	2-3
2.1.3 Physical Habitat Assessment	2-4
2.1.4 Biological Monitoring	2-5
2.1.5 Supplemental Data from the Maryland Biological Stream Survey	2-7
2.2 <u>Other Study Methods</u>	2-7
2.2.1 Geologic Characterization	2-7
2.2.2 Land Use, Land Cover, and Vegetation Analysis	2-7
2.2.3 Wildlife and Threatened and Endangered Species	2-9
2.2.4 Visual Inspection for Potential Watershed Stressors	2-9
2.2.5 Infrastructure Analysis	2-11
2.2.6 Inventory of Pollutant Sources	2-11
2.2.7 Zoning and Population Projections	2-11
3.0 DESCRIPTION OF THE WATERSHED	3-1
3.1 <u>Geological Setting</u>	3-1
3.1.1 Topography	3-1
3.1.2 Soils	3-2
3.2 <u>General Land Uses</u>	3-3
3.3 <u>Vegetation and Land Cover</u>	3-5
4.0 ASSESSMENT OF EXISTING CONDITIONS IN LOWER BUSH CREEK WATERSHED	4-1
4.1 <u>Biological, Chemical, and Physical Assessment of Selected Stream Sites</u>	4-1
4.2 <u>Additional Stream Data from Maryland Biological Stream Survey</u>	4-9
4.3 <u>Wildlife</u>	4-11
4.4 <u>Threatened and Endangered Species</u>	4-12
4.5 <u>Visual Inspection for Watershed Stressors</u>	4-14
4.6 <u>Infrastructure Analysis</u>	4-15
4.6.1 Water and Sewer Service	4-15
4.6.2 Transportation	4-26
4.7 <u>Inventory of Pollution Sources</u>	4-26
4.7.1 Stormwater Management Facilities	4-27
4.7.2 Individual Permitted Discharges	4-27

4.7.3	Nonpoint Pollution from Development	4-28
4.7.4	Pasture and other Agricultural Impacts	4-29
4.7.5	Potential Sources of Contaminants	4-30
4.8	<u>Zoning and Population Projections</u>	4-31
4.8.1	Existing Land Use	4-31
4.8.2	Existing Population	4-36
4.8.3	Population Projections	4-37
4.8.4	Future Land Use	4-40
4.9	<u>Estimates of Impervious Surface in Watershed</u>	4-42
5.0	ASSESSMENT AND RANKING OF WATER QUALITY PROBLEMS	5-1
6.0	IDENTIFICATION OF OPPORTUNITIES TO IMPROVE WATER QUALITY	6-1
7.0	WATERSHED WATER QUALITY PLAN	7-1
7.1	<u>Integration of Watershed Assessment Results</u>	7-1
7.2	<u>Proposed Actions to Improve Water Quality</u>	7-1
7.3	<u>Monitoring to Evaluate Effectiveness of Water Quality Improvements</u>	7-7
8.0	REFERENCES	8-1
 APPENDICES		
A	PHOTOGRAPHIC LOG OF THE WATERSHED MONITORING STATIONS	A-1
B	SPECIES FOUND WITHIN THE WATERSHED	B-1
C	PHOTOGRAPHIC LOG FOR THE VISUAL INSPECTION	C-1